Handover notes

Boat Console - exported 2026-11-25

id	Title	Note	Pin to top of the overview
2	Watermaker salinity	Product ppm rising since the last membrane change. Check HP pump seals before blaming the new membranes.	1
1	Read me first - boat handover	Use this note for everything a new engineer should know on day one. Edit it! - Where the main breakers / battery isolators are: - Emergency procedures (fire in engine room, flo...	1