Unplanned maintenance

Boat Console - exported 2026-11-25

id	Defect	Equipment	Description	Priority	Status	Reported by	Reported	Closed	Resolution
1	Product salinity creeping up (480 ppm)	Watermaker		High	Open	Jamie Cole	2026-11-15		
4	Guest cabin AC unit tripping on high pressure	Air conditioning		Normal	In progress	Jamie Cole	2026-11-12		
2	Intermittent fault on bow thruster joystick	Bow thruster		Normal	Waiting parts	Alex Moreno	2026-11-08		
3	Forward cabin hatch seal weeping in heavy rain	Hatches & portlights		Low	Open	Priya Shah	2026-11-03		
5	Stern light LED flickering	Navigation lights		Low	Closed	Alex Moreno	2026-10-28	2026-10-31	Replaced LED fitting.